

**NOTE** Fill to within 1.50-2.00  
of top of reservoir to eliminate  
excessive spillage.

FENDER TO RAD-  
IATOR SUPPORT  
SCREW UPC 11-13

.196/.199 DIA 2 HOLES IN  
RADIATOR SUPPORT  
THRU EXISTING  
DIMPLES.

RADIATOR  
SUPPORT

P/S PUMP

GEN

.58 MIN TO GEN.

.60 MIN TO SKIRT

SKIRT

GEN BRACKET  
SCREW UPC 6

on 2 20° outboard  
gear centerline.