

Click the links for related parts

NOTE Fill to within 1.50-2.00 of top of reservoir to eliminate excessive spillage.

FENDER TO RAD-
IATOR SUPPORT
SCREW UPC 11-13

.196/.199 DIA 2 HOLES IN
RADIATOR SUPPORT
THRU EXISTING
DIMPLES.

RADIATOR
SUPPORT

P/S PUMP

GEN

.58 MIN TO GEN.

.60 MIN TO SKIRT


SKIRT **OR**

GEN BRACKET
SCREW UPC 6

on **2** 20° outboard
gear centerline.

GROUND UP
SS396.COM
866-388-2277

Click the links for related parts



OR

OR